

# Weekly incident summary

# Week ending 3 March 2023

This incident summary provides information on reportable incidents and safety advice for the NSW mining industry. To report an incident to the NSW Resources Regulator: phone 1300 814 609 24 hours a day, 7 days a week.

# At a glance

High level summary of emerging trends and our recommendations to operators.

Туре	Number
Reportable incident total	59
Summarised incident total	5

# Summarised incidents

### Incident type Summary Comments to industry Dangerous incident A fire started in a shed at a batch plant at an Mine withdrawal plans and underground metalliferous mine. The mine trigger action response plans IncNot0044225 evacuated all personnel on the surface, as there (TARPS) must be in place and Underground metal was the potential for the smoke to enter the tested regularly. decline. Those workers underground went to mine Hazardous chemicals need to refuge chambers. be appropriately stored, Fire or explosion Emergency services were called, and the fire bunded, labelled and was extinguished. Chemicals that were stored in signposted. Housekeeping the area contributed to the fuel load of the fire. standards around chemical storage areas must be maintained and inspected. Firefighting systems need to be inspected regularly and maintained.

### Incident type

### Summary

### Comments to industry



Dangerous incident IncNot0044173 Underground metal mine A fourth year mechanical apprentice was removing hoses on the retrieval circuit of a load haul dump (LHD). While undoing a hose, high pressure hydraulic oil sprayed the apprentice's left arm. The apprentice was cleared of injury.



Workers must ensure hydraulic systems are isolated and stored pressure is released before working on hydraulic systems.

Apprentices must be supervised and trained in workplace tasks.

Dangerous incident IncNot0044171

Underground metal mine

Inundation or inrush of any substance

While loading from a draw point, an uncontrolled flow of material came from the draw point. The flow started slowly and flowed back into the drive.

Mine operators must assess the risk of inrush and inundation. When the risk exists, a principal hazard management plan must be in place.

Refer to the code of practice <u>Inundation and inrush hazard</u> <u>management</u>

### Incident type



### Comments to industry





Dangerous incident IncNot0044167 Open cut coal mine Ground or strata failure





Mine designs should be guided by a robust geotechnical assessment, conducted by a qualified person. Geotechnical assessments and reviews should be conducted at appropriate intervals.

Where geotechnical hazards are known to exist, monitoring systems should be installed and monitored, with an early warning capability.

Clear withdrawal conditions (such as a TARP) should be part of any ground or strata failure principal hazard management plan.

Dangerous incident IncNot0044166 Underground metal mine

Roads or other vehicle operating areas

A light vehicle was driving down a decline when the vehicle made contact with the wall. Preliminary information suggests an issue with the brakes. No workers suffered any injuries.

Vehicles need to be fit-forpurpose with regular maintenance and inspection systems in place. This must include critical systems such as steering and brakes.

Operational testing of service and park brakes should be included in pre-use inspections.

# Incident type Summary Comments to industry

**Note:** Please ensure all relevant people in your organisation receive a copy of this safety alert and are informed of its content and recommendations. This safety alert should be processed in a systematic manner through the mine's information and communication process. It should also be placed on the mine's common area, such as your notice board where appropriate.

Visit our website to:

- find more safety alerts and bulletins
- use our searchable safety database

## Other Resources Regulator publications

### Safety Alert SA23-01 Unintended movement of haul truck

An operator of an MT4400 haul truck left the cabin and descended the main stairs to isolate the truck in response to alarms, and walked in front of the truck to the main isolator on the off driver's side front bumper. The truck was not parked on level ground and started to roll forward when the battery isolator was turned off. The operator ran back in front of the rolling truck and up the main stairs to the cabin to apply the service (foot) brake. The incident occurred on 19 February 2023.

Read the full report on our website

### Changes to certificate of competence exam calendar 2023

The calendar has been changed for exams in 2023 on our website including:

- undermanager written exams will be held over 2 days (29 & 30 March) and the oral exams are now the 5 & 6 June
- OCE and mining engineering manager coal mines briefing session 14 March
- underground mine supervisor briefing session 20 March (note applications close 12 April)
- quarry manager briefing session 19 June
- mechanical engineering briefing session 20 June

All applications are to be submitted via the Resources Regulator <u>portal</u> by first obtaining a login, which requires identity documents to be submitted.

Individuals interested in applying are recommended to attend the free face to face only briefing session for each function conducted by each examination panel to inform you of what the process requires and what is expected to be assessed as competent. Please register to attend in person by this link:

### https://cocbriefingsesstickets.eventbrite.com.au

Note: the session will not be recorded and a copy of the presentation will only be provided to those who attend in person.

Please contact the mining competence team for further information <a href="mailto:mca@regional.nsw.gov.au">mca@regional.nsw.gov.au</a> or 1300 814 609 (options 2 & 3).

### Further audits of WHS practising certificate holders for maintenance of competence

The Resources Regulator is contracting external organisations to conduct a further 100 audits by 30 June 2023 of practising certificate holders for their condition to comply with the gazetted maintenance of competence requirements.

Up to 10% of practising certificate holders for each statutory function with certificates expiring in the 2023-2024 financial year will be audited randomly.

For more details refer to our <u>Fact sheet: Auditing of WHS practising certificate holders</u> on our maintenance of competence webpage.

For specific enquiries, you can email <u>mca@regional.nsw.gov.au</u> or phone 1300 814 609 (options 2 and 3).

# Other publications of interest

The incidents are included for your review. The NSW Resources Regulator does not endorse the findings or recommendations of these incidents. It is your legal duty to exercise due diligence to ensure the business complies with its work health and safety obligations.

Publication	Issue/topic
	National (other, non-fatal)
Resources Safety & Health Queensland	The Petroleum and Gas Inspectorate (PGI) has conducted Noise Health Risk Assessments (HRAs) across several operating plants to establish a baseline for hazardous noise. Noise-induced hearing loss (NIHL) is caused by exposure to loud noises over a period depending on the loudness, pitch, and length of time. NIHL is painless, progressive, permanent, and preventable.  Details
Resources Safety & Health Queensland	A mobile processing unit fitted with a dual fuel fill system was fitted with a faulty fuel cap. The fuel cap was missing the rubber seal, which created a potential fire hazard.
	An oversight has failed to identify the fuel cap for the gravity feed refuelling system was missing a rubber seal. The seal is critical to maintaining fuel tank pressurisation during the fast fuel process.
	Key issues: When the rubber seal is missing from the gravity feed fuel cap, increased pressure from the fast fuel process may cause fuel to spill from the gravity feed fuel cap. A previous incident resulted in a spill of diesel fuel from a defective gravity feed fuel cap onto hot engine parts, causing a fire and full loss of the charge up vehicle.  Details

Note: While the majority of incidents are reported and recorded within a week of the event, some are notified outside this time period. The incidents in this report therefore have not necessarily occurred in a one-week period. All newly recorded incidents, whatever the incident date, are reviewed by the Chief Inspector and senior staff each week. For more comprehensive statistical data refer to our annual performance measures reports.

© State of New South Wales through Regional NSW 2023. You may copy, distribute, display, download and otherwise freely deal with this publication for any purpose, provided that you attribute Regional NSW as the owner. However, you must obtain permission if you wish to charge others for access to the publication (other than at cost); include the publication in advertising or a product for sale; modify the publication; or republish the publication on a website. You may freely link to the publication on a departmental website.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (March 2023) and may not be accurate, current or complete. The State of New South Wales (including Regional NSW), the author and the publisher take no responsibility, and will accept no liability, for the accuracy, currency, reliability or correctness of any information included in the document (including material provided by third parties). Readers should make their own inquiries and rely on their own advice when making decisions related to material contained in this publication.

Document control	
CM9 reference	RDOC23/63908
Mine safety reference	ISR23-09
Date published	10 March 2023
Authorised by	Deputy Chief Inspector Office of the Chief Inspector