

# Weekly incident summary

## Week ending 23 May 2025

This incident summary provides information on reportable incidents and safety advice for the NSW mining industry. To report an incident to the Resources Regulator: phone 1300 814 609 24 hours a day, 7 days a week.

### At a glance

High level summary of emerging trends and our recommendations to operators.




Type	Number
Reportable incident total	39
Summarised incident total	3

### Summarised incidents

Incident type	Summary	Comments to industry
Dangerous incident IncNot0049152 Open cut coal mine Roads or other vehicle operating areas	<p>A dozer was doing a clean-up for an excavator while the excavator was loading a dump truck.</p> <p>A second dump truck entered the area and went into the queue about 30 metres from where the truck was being loaded.</p> <p>The dozer operator reversed to turn and leave the work area, and collided with position 6 tyre of the queued truck. The dozer operator had not identified that the second truck had entered the work area.</p>	<p>Situational awareness is a key control when operating mobile equipment. Workers should be trained in the importance of this control and include it in their pre-task risk assessments.</p> <p>Mine operators should continually review the suitability of collision avoidance technology as it evolves, and new products become available.</p> <p>Operators should prioritise segregation between dozers and haul trucks over lower order controls such as positive communication and work procedures.</p> <p>Refer to: Safety bulletin <a href="#">SB24-01 Bulldozer incident increase</a></p>



Weekly incident summary week ending 23 May 2025

Incident type	Summary	Comments to industry
<div><div></div><div><p>Dangerous incident IncNot0049141</p><p>Underground coal mine</p><p>Roads or other vehicle operating areas</p><div></div></div></div> <div><p>An old shearer body (with no counterweight or ranging arms) was loaded onto a heavy haulage truck using a forklift.</p><p>The left and right shearer haulage sprockets and trapping shoes were positioned on the gate end/transition pans that have a larger clevis arrangement on the back of the pan set.</p><p>Once the load was dogged down and cleared for transport, the truck was driven about 300 metres and rolled, while driving at slow speed on flat ground around a left-hand corner.</p><p>The driver was uninjured.</p><p>Two gate/transition pans were used instead of run-of-face (ROF) pans for the sprockets to sit on. This shifted the load towards one side, shifting centre of balance.</p><div></div></div> <div><p>Operators must identify the risk of loads shifting due to an imbalance, especially when there is steel-on-steel contact.</p><p>Mine operators should have a procedure for transporting shearers that specifies the appropriate pans to use for transport purposes. Secure loading should not be the sole responsibility of the transport driver who may not be familiar with the equipment.</p><p>In this instance, the load was well secured but the centre of balance was off.</p></div>		

## Weekly incident summary week ending 23 May 2025

Incident type	Summary	Comments to industry
		
<p>Dangerous incident IncNot0049157 Open cut coal mine Roads or other vehicle operating areas</p> 	<p>A haul truck was passing a drill rig that was tramping along a haul road when the position 2 tyre and the mast of the drill rig collided.</p> <p>The truck operator saw an indicator light flash on the drill rig and assumed that it was a signal to pass.</p> 	<p>To achieve positive communication, a clear direct message must be given. Additionally, the person receiving the message must actively reply with a clear understanding of the message.</p> <p>Supervisors should be continually monitoring positive communication compliance during every radio call on their shift.</p> <p>Work Health and Safety Regulation 2017 section 35 and 36 require higher order risk controls to be implemented and administrative controls such as positive communication, only to be used when no higher order controls can be implemented.</p> <p>Controls such as equipment segregation and proximity awareness systems should be implemented before positive communication are considered.</p>

## Other Resources Regulator publications

### Recent increase in heavy vehicle rollovers

The Resources Regulator in NSW has issued a safety bulletin following a concerning increase in heavy vehicle rollovers in the past 12 months throughout all sectors of the NSW mining industry.

Vehicle interactions are showing an increasing trend as evidenced by 40 incidents that were notified to the Resources Regulator. Of the 40 incident notifications, 21 were from coal mines, 12 were from construction, 5 were from metalliferous mines and 2 were from industrial minerals.

[Read the full safety bulletin and recommendations. \(PDF, 721.26 KB\)](#)

## Weekly incident summary week ending 23 May 2025

### Investigation report published after entanglement incident

The Resources Regulator in NSW has published an investigation report into an incident in which a worker suffered the amputation of his left arm when it became entangled on the rotating drill steel of a jumbo drill rig on 19 June 2023.

The incident occurred at Cadia East Underground Mine near Orange in NSW. The investigation found a number of factors contributed to the worker being exposed to the risk of serious injury or death.

[Read the full report and recommendations to industry \(PDF, 791.68 KB\).](#)

### Other publications of interest

The incidents are included for your review. The Resources Regulator does not endorse the findings or recommendations of these incidents. It is your legal duty to exercise due diligence to ensure the business complies with its work health and safety obligations.

Publication	Issue/topic
	<b>National (other, non-fatal)</b>
<b>Business Queensland</b>	<b>Mineral Mines and Quarries quarterly report published</b> The latest Queensland Mineral Mines and Quarries inspectorate quarterly report has been released with updates on: <ul style="list-style-type: none"><li>• regulator activity</li><li>• statistics</li><li>• serious accidents</li><li>• high potential incidents</li><li>• incident focus – worker received leg injury from fall of suspended load</li><li>• incident focus – unplanned movement of load</li><li>• incident focus – dump truck brake failure</li><li>• interstate and global updates</li><li>• health hub – underground mines: respirable dust and respirable crystalline silica</li><li>• people to controls electrical work forum 2025</li><li>• key training</li><li>• key engagement and activities.</li></ul> <a href="#">Details</a>

Note: While the majority of incidents are reported and recorded within a week of the event, some are notified outside this time period. The incidents in this report therefore have not necessarily occurred in a one-week period. All newly recorded incidents, whatever the incident date, are reviewed by the Chief Inspector and senior staff each week. For more comprehensive statistical data refer to our annual performance measures reports.

# Weekly incident summary week ending 23 May 2025

© State of New South Wales through the Department of Primary Industries and Regional Development 2025. You may copy, distribute, display, download and otherwise freely deal with this publication for any purpose, provided that you attribute the Department of Primary Industries and Regional Development 2025 as the owner. However, you must obtain permission if you wish to charge others for access to the publication (other than at cost); include the publication in advertising or a product for sale; modify the publication; or republish the publication on a website. You may freely link to the publication on a departmental website.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (May 2025) and may not be accurate, current or complete. The State of New South Wales (including the Department of Primary Industries and Regional Development 2025), the author and the publisher take no responsibility, and will accept no liability, for the accuracy, currency, reliability or correctness of any information included in the document (including material provided by third parties). Readers should make their own inquiries and rely on their own advice when making decisions related to material contained in this publication.

Document control	
ISSN:	2982-1010 (online)
CM10 reference	D25/31431
Mine safety reference	ISR25-21
Date published	30 May 2025
Authorised by	Deputy Chief Inspector Office of the Chief Inspector