## MDG 2 – Locomotive Incidents

Incident	Agent of	Events	Recommendations
Information	fatality		
OPEN CUT MINES			
22/10/2007 United States Non-Coal Open-Cut	Other	Miner was walking across a rail yard to uncouple loaded railway cars when he was struck by a yard locomotive.	
19/02/2007 United States Non-Coal Open-Cut	Other	Victim was on loaded train cars when they struck a haul truck which was crossing the track.	Management should ensure they have traffic control policies and enforce these.
28/11/2005 New Zealand Non-Coal Open-Cut	Other	Victim riding on rail carriage fell off when rake of wagons jolted	
18/08/2004 United States Non-Coal Open-Cut	Other	Deckhand was killed when fatally struck by moving railcars while repositioning them.	Perform risk assessment to identify hazards before moving railcars and a safe work procedure for moving railcars.
6/08/2002 United States Non-Coal Open-Cut	Contact with Moving or Rotating Plant (Guarding/Access to Danger Zone)	A contract switchman was fatally injured at a trona mine. The accident occurred at night. The victim, switching cars at a surface load out area, was caught between a 15-car train he was riding and a stationary car as the train moved.	Provide illumination to recognize hazards in work areas. Identify possible hazards and safe work procedures before moving rail cars. Provide communications between personnel assigned to move rail cars. Maintain a clearance at least 30" between equipment.
7/08/2001 United States Non-Coal Open-Cut	Contact with Moving or Rotating Plant (Guarding/Access to Danger Zone)	A utility man was fatally injured when he was pinned between a rail car and tractor coupling. After noticing a coupling had disengaged, the victim directed the driver back and attempted to reconnect when the rail cars rolled, pinning him.	Rail cars to be isolated prior to persons travelling or working in hazardous area. Couplings used to attach mobile equipment to rail cars to be provided with controls that open and close coupling without exposure to injury.
19/09/1999 United States Coal Underground	Other	A mechanic was fatally injured while unloading rail locomotive power assemblies from a flat bed service truck. Victim lost his balance and grabbed one of power assemblies. Unstable assemblies and victim fell off truck. One of assemblies hit victim in head	Ensure there is adequate space to work. Stabilize heavy machinery before applying rigging. Utilize adequate lifting devices for the type of work to be performed.
1/07/1998 United States Non-Coal Open-Cut	Unintended Operation of Equipment	A serviceman was fatally injured when his road sweeper was struck by a train. Accident occurred in a rail tunnel beneath a cement storage silo. Train begun backing through tunnel when it hit sweeper; pinning sweeper with driver inside against tunnel wall.	Prior to moving trains a warning to be sounded. Where restricted clearance creates a hazard to persons on mobile equipment the restricted area to be conspicuously marked. Rules governing the direction of movement be established and followed.

4/05/1998 United States Non-Coal Open-Cut	Contact with Moving or Rotating Plant (Guarding/Access to Danger Zone)	A mechanic was fatally injured at a stone quarry. The victim was performing repairs under a rail car when a remotely controlled locomotive impacted the car. The victim was run over when he attempted to crawl out from under the car.	Derailing devices be installed between workers on rail cars and moving equipment. A warning to be sounded prior to moving trains. Remote controlled locomotives only to be used when operator can maintain visual contact with locomotive and all cars.
20/10/1997 United States Non-Coal Open-Cut	Unintended Operation of Equipment	A leadman was fatally injured cleaning the weigh scale in front of a 125T locomotive and ten cars that were not isolated from movement. When four cars were attached to the rear of the parked train, it moved forward and the engine ran over him.	Before commencing work on equipment or near equipment, the equipment must be appropriately isolated, chocked and or locked out in accordance with isolation procedures.
24/07/1997 United States Non-Coal Open-Cut	Uncontrolled Release of Energy	A mechanic was fatally injured while assisting 2 other mechanics replace brake shoes on a rail road engine. The engine had been hoisted by a crane and blocked with 4x4 inch wooden blocks. The engine rocked and fell off the block, landing on the mechanic.	
4/10/1996 United States Non-Coal Open-Cut	Contact with Moving or Rotating Plant (Guarding/Access to Danger Zone)	A weighmaster was fatally injured when it was believed victim attempted to set or release brakes on the open-top rail cars which were to be taken for loading. He fell between rail cars and was found lying across tracks pinned by wheel of a rail car.	All employees should be trained in work safe procedures. Before attempting a hazardous task all people involved in work place should be notified
14/04/1966 Australia New South Wales Coal Open-Cut	Other	Was assisting to unload a battery operated mini locomotive when the trolley started to move, flung off the electrician and struck him in the head as it passed, killing him.	
1/01/1963 Australia New South Wales Non-Coal Open-Cut	Other	Run over by a steel skip on which he was riding, and was thrown from the skip	
1/01/1956 Australia New South Wales Coal Open-Cut	Unintended operation of Equipment	Haulage motor failed to stop an alligator in which the deceased had been riding, and it fell on him	
1/01/1956 Australia New South Wales Coal Open-Cut	Other	Fell under a train on which he had been riding	

UNDERGROUND MINES			
21/04/2006 United States Coal Underground	Unintended Operation of Equipment	Electrician was checking hydraulic pressure on tram while outside operator compartment and the tram was caused to move, trapping him against a belt Conveyor.	Development and implementation of a maintenance plan hen operating on equipment.
7/04/2006 United States Coal Underground	Fall of Roof/Sides/Highwall	Superintendent was operative locomotive along mine track when he struck a 4 inch I beam hanging from the mine roof in a close clearance area.	Proper installation of crossbars and change of the roof control plan, pre-shift workplace safety examinations.
17/02/2006 United States Coal Underground	Unintended Operation of Equipment	Bolting machine operator fatally injured when crushed between his locomotive and a longwall shield sitting idle on rail car which was hanging off the side of the rail car.	Longwall shields must be transported safely and trip lights on all loads which do not use tailmotors, hazard training.
16/06/2004 United States Coal Underground	Other	Victim was washing loose raw coal material off bunker car when he became crushed between bunker car and steel beam.	Removal of the upright channel, installation of visual and auditory sound when cars are going to move and also egress cords to stop movement.
20/11/2001 United States Coal Underground	Other	While conducting track maintenance and installing new rail, a miner was fatally injured when a rail car struck him. A co-worker was attempting to move a locomotive when the brake was released and it drifted backwards hitting miner conducting maintenance.	Equipment operators to be certain all persons are clear before moving equipment. Operator of self-propelled equipment to give a warning where movement of equipment may endanger persons.
8/11/2001 United States Coal Underground	Unintended Operation of Equipment	A general inside labourer was fatally injured when 3 rail mounted supply cars ran away after becoming uncoupled from brake car.A safety chain on brake car also failed.3 loaded supply cars travelled into mine through derail device, striking victim at bottom.	Regularly check couplers for wear to not exceed tolerances specified by manufacturer. Use safety chains rated for applicable load. Check derail devices to assure effectiveness. Install alarms to notify persons supplies are being lowered into mine.
6/11/2000 United States Non-Coal Underground	Other	A 36-year-old miner with 18 years mining experience was fatally injured at an underground gold mine. The victim was operating a 1 1/2 ton battery locomotive when his head struck a wooden ore chute that protruded out into the drift.	Conspicuous markings should be installed where restricted clearance presents a hazard to persons.
21/09/2000 United States Coal Underground	Unintended Operation of Equipment	A mechanic received fatal injuries when he was crushed between a coal car and corner of a rotary dump. Victim was attempting to troubleshoot an alignment problem on a rotary dump. On separating a rail car, another car drifted back and crushed victim.	Equipment operators to be aware of location of all individuals involved in task prior to moving equipment. Equipment to be isolated sufficiently prior to commencing work. In cases where equipment is to be running, safe work procedures are to be used.

13/03/2000 United States Non-Coal Underground 23/12/1998 United States Non-Coal Underground	Contact with Moving or Rotating Plant (Guarding/Access to Danger Zone) Unintended Operation of Equipment	A 48-year-old motorman with 24 years mining experience was fatally injured at an underground platinum mine. The victim was walking in front of a string of empty cars that were being pushed into position for loading when he was struck by the lead car. A utility man was fatally injured when crushed between a loader and a loaded rail car. The rail car he was towing continued to roll after the loader had stopped. Victim was crushed when slack in cable was	A clearance to be maintained on side of equipment when moving along haul roads. Haul roads be kept free of debris. Communications to be maintained between equipment operators. Trains not to be moved until there is verification that all persons are in clear. Mobile equipment operators should maintain control of the equipment while it is in motion. A rigid coupling designed for rail equipment to be used to tow rail cars. Personnel assigned to
8/11/1998 Canada Non-Coal Underground	Contact with Moving or Rotating Plant (Guarding/Access to Danger Zone)	taken up, jerking loader bucket against rail car. The worker was working at a waste dump at the controls of a pneumatic car-dumper while his partner was backing up a haulage train to the dump position. The victim was caught and squeezed between side of haulage car and cylinders of the pneumatic dumper.	work with rail cars should be trained in safe work procedures.
15/01/1998 United States Coal Underground	Unintended Operation of Equipment	A loaded supply car being pulled to mine surface uncoupled from a tram motor. A safety rope between car and motor also failed. Supply car travelled down incline colliding with a man car inflicting fatal injuries to a section mechanic.	A preoperational inspection to be conducted of track haul equipment, including couplings and safety chains. When defects affecting safety are found, defects to be corrected before operation. Equipment operators should ensure tracks are clear before proceeding.
27/10/1996 United States Coal Underground	Unintended Operation of Equipment	A supply motorman was fatally injured operating a locomotive. Victim was transporting longwall shields out of mine to surface. One of shields protruded past carrier it was on. Motorman stopped loco on surface and loco crashed into end of trip and victim.	
26/10/1996 United States Coal Underground	Uncontrolled Release of Energy	A labourer was fatally injured operating a 20T locomotive. Victim was moving a 4T longwall equipment sled on supply cars connected to loco. Sled was attached to cars with chain which during transportation broke, allowing sled to move and hit operator.	
17/06/1995 United States Coal Underground	Unintended Operation of Equipment	Unloading coal cars through a rotary dump system; a dump operator was fatally injured when a car became uncoupled. Using car haul, operator pulled remaining cars up a slight grade so he could realign coupler. Loaded cars ran down and crushed operator.	Stopblocks be provided on loaded sides of rotary dumps to protect persons from runaway equipment. Regular maintenance of equipment should take place to ensure safe operation. Hazard risk management should be implemented and safe work procedures developed.

1000			
1989	Unintended operation	A locomotive was pushing two stone	
Australia	of Equipment	dusting trolleys into the mine without	
New South Wales		coupling them and they ran away	
Coal		then they hit the down grade and	
Underground		struck a personnel carrier on the	
C		tracks going into the mine.	
10/12/1988	Other	A locomotive was not attached to 2	
Australia		carriages of stonedust it was pushing	
New South Wales		into the mine when it hit the slope	
Coal		and accelerated away. It struck a	
Underground		personnel car some 800m down	
Chuerground		track, killing the deputy who was	
		driving at the time.	
1007	I Inintan da d'an anation		
1987	Unintended operation	Deputy jumped from his personal car	
Australia	of Equipment	when he realised a collision with a	
New South Wales		locomotive was imminent and was	
Coal		trapped between his car and the coal	
Underground		rib.	
22/10/1986	Other	Deputy was driving his personal car	
Australia		when he collided with a locomotive	
New South Wales		at a turn	
Coal			
Underground			
28/01/1986	Other	While riding in the drivers' cabin of	
Australia		locomotive, it struck bin flap gates	
New South Wales		which had not been raised following	
Coal		previous load and killed passenger.	
Underground			
1986	Unintended operation	Runaway locomotive fatally injured a	
Australia	of Equipment	workman down track.	
New South Wales	or Equipment		
Coal			
Underground			
1986	Other	A locomotive ran into an open bin	
Australia	Ouler	door which fatally injured the loco	
New South Wales		driver.	
		unver.	
Coal			
Underground	Other		
7/12/1985	Other	A locomotive was driven down a	
Australia		slope with another hauling a man	
New South Wales		transport behind. A swilly on the	
Coal		track caused both locomotives and	
Underground		man transport to de-rail and the	
		driver of the first locomotive was	
		thrown from his transporter and died.	
3/03/1985	Other	Victim was standing on train trolley	
Australia		next to LHD when the LHD engaged	
New South Wales		a steel roof support triggering a roof	
Coal		fall while loading the train which	
Underground		crushed the machine man.	
17/01/1985	Fall of	Locomotive driver did not put in	
Australia	Roof/Sides/Highwall	place shoes which slow the train	
New South Wales	L Č	down a slight gradient prior to	
Coal		motion and the train moved out of	
Underground		control down the slope. He was	
- mar Brownia		killed when he jumped out of the	
		carriage 600m down the slope.	
		currage ocom down the slope.	

		1	
23/10/1984	Other	Was riding in a Speno Rail Grinder	
Australia		when it came upon a stationary ore	
Western Australia		train. Three of the four jumped clear	
Non-Coal		and one struck his head upon	
Underground		landing.	
7/02/1984	Other	Driver was leaving mine in	
Australia		locomotive when it struck a steel	
New South Wales		cross support which fell and took out	
Coal		the driver.	
Underground			
1983	Other	Was repairing an incline work road	
United Kingdom		when he was struck by a runaway. It	
Coal		is apparent that he should have	
Underground		erected runaway protection before	
Chucigiounu		the commencement of the	
		maintenance.	
17/12/1981	Fall from Heights	Fell 474m down the service	
Australia	r an nom neights	compartment of the shaft with a	
Western Australia		battery loco.	
Non-Coal			
Underground	Other	Estally initian database the local data	
2/12/1981	Other	Fatally injured when the loaded ore	
Australia		train he was driving crushed into a	
Queensland		stationary work platform.	
Non-Coal			
Underground			
13/04/1981	Catastrophic Failure	Driver was killed when a new	
Australia		locomotive's brakes failed after being	
New South Wales		put into service without proper	
Coal		service facilities.	
Underground			
1981	Other	Fatally injured when he was engaged	
United Kingdom		in re-railing a derailed supplies	
Coal		vehicle loaded with 4.4 tonnes of	
Underground		material at the junction of a	
		Conveyor road dipping at 1 in 5 and	
		a cross cut. While performing this,	
		the vehicle slipped and he was	
		crushed against the Conveyor	
		structure.	
30/11/1979	Catastrophic Failure	Workman was fatally injured when	
Australia		hit by metal skip which ran away	
New South Wales		downgrade after a coupling and	
Coal		safety chain had failed.	
Underground			
10/10/1979	Other	Workmen were run down during roof	Barriers and warning signs and
Australia		bolting operations on a transport	lights used when bolting in an
New South Wales		roadway when they were struck by a	enclosed and poorly lit area.
Coal		loaded locomotive.	
Underground			
21/11/1978	Other	Manriding Train Derailment	
United Kingdom			
Coal			
Underground			
11/05/1977	Other	Killed when he stepped back into the	
New Zealand		path of a locomotive	
Unknown		<b>`</b>	
Underground			
l	1		l

40			1
1977	Unintended operation	Collision between a battery	
Australia	of Equipment	locomotive and stationary diesel	
New South Wales		tractor parked on roadway	
Coal			
Underground			
1977	Other	Was run over by a descending	
Australia		alligator skip in a drift drivage	
New South Wales			
Coal			
Underground			
1977	Other	Three large powered supports	
United Kingdom		mounted on bogie wheels ran away	
Coal		down a drift, after demolishing three	
Underground		Warwick girders struck and killed a	
		workman.	
1976	Catastrophic Failure	Was killed when the connecting rope	
United Kingdom	1	between the two elements of a double	
Coal		acting Warwick broke, allowing one	
Underground		of the girders to fall on him.	
1976	Other	Was killed while he was operating a	
United Kingdom		Warwick girder on a captive rail	
Coal		installation and a heavy and awkward	
Underground		load overturned and crushed him	
		against the side.	
1976	Other	Guard failed to see a dislodged prop	Do not operate trains without
United Kingdom		in time, which was protruding onto	proper illumination
Coal		the track, due to having no light on	proper memory
Underground		the train except for a headlamp. All 3	
Chucigiounu		men jumped from the train and one	
		received fatal head injuries.	
1975	Other	Passenger was thrown from battery	
Australia	ouloi	locomotive when it derailed at set of	
New South Wales		defective points. Would not have	
Coal		been thrown off if there was not extra	
Underground		passenger travelling.	
1975	Unintended operation	Killed when he was thrown off upon	
Australia	of Equipment	derailment after a turn and it careered	
New South Wales	of Equipment	down an inclined roadway. Tracks	
Coal		had been saturated by water to clean	
Underground		Conveyor belts in roadway.	
16/06/1972	Unknown	Was found dead inside an empty	
Australia		mine truck when a race of empty	
New South Wales		trucks arrived at the top of an incline	
Coal		operated by a winch	
Underground		operated by a which	
1972	Other	After jumping from a battery	
New Zealand		locomotive a miner was killed	
Coal		driving into the mine. There were no	
Underground		faults, problems or overloads with	
- navi și vunu		the machine.	
1971	Unintended operation	He derailed a battery locomotive on a	
Australia	of Equipment	turn with excessive speed the only	
New South Wales	or Equipment	cause.	
Coal			
Underground			
20/04/1970	Gas Ignition	Mathana avalagion ignited by a	
United States	-	Methane explosion ignited by a trollow or motor	
	Explosion	trolley or motor	
Coal			
Underground			
1			

1970	Other	Killed by a runaway man transport	
Australia		car. Transport was being shunted in	
New South Wales		order to position a locomotive outby	
Coal		of the car when it ran away and	
Underground		slammed into the visitor group.	
1970	Unintended operation	Jumped from a battery locomotive	
Australia	of Equipment	hauling three skips of stone which	
New South Wales	1 1	got out of control	
Coal		0	
Underground			
1970	Other	A runaway locomotive and trollier	
Australia		were involved in a derailment due to	
New South Wales		load weight, inability to place shoes	
Coal		and driver inexperience	
Underground			
1969	Other	Fell and was trapped beneath an	
Australia	other	electric battery locomotive on which	
New South Wales		he had been riding. He was riding in	
Coal		an uncomfortable part on the front	
Underground		when he was dislodged by a bump. It	
Shuvigi bunu		was not designed to carry that many	
		people.	
1968	Unintended operation	Locomotive and two mine cars were	
Australia	of Equipment	derailed after running backwards out	
New South Wales	or Equipment	of control on the transport road. The	
Coal		deceased was illegally riding on the	
Underground		carriage without driver knowledge.	
Underground		Maximum loads have been reduced	
1967	Other	to prevent future re-occurrence.	
	Other	Was fatally injured at the foot of a jig	
New Zealand		when he was hit by a runaway box of	
Coal		coal	
Underground		XX7 1 1 4 4 1	
1965	Unintended operation	Was run over by a battery operated	
Australia	of Equipment	prime mover which went out of	
New South Wales		control when a control lever was	
Coal		jammed in the 'on' position. This then	
Underground		careered through a crib room and	
		struck a worker.	
1965	Other	Acting as a shunter and fell from the	
Australia		rear of a moving locomotive beneath	
New South Wales		a trolley loaded with rails which were	
Coal		being hauled by the locomotive.	
Underground			
29/04/1963	Unintended operation	Acting as a locomotive driver, the	
Australia	of Equipment	locomotive got out of control and	
New South Wales		derailed, knocking out a lot of baulks	
Coal		and crushed the operator against one	
Underground			
8/05/1962	Other	Riding on locomotive when a door	
Australia		opened on a turn and caught a rail,	
New South Wales		causing loco to lurch	
Coal			
Underground			
10/03/1962	Contact with Moving	Trolley, on which a pump was	
Australia	or Rotating Plant	mounted became derailed while	
New South Wales	(Guarding/Access to	being transferred from one part of the	
Coal	Danger Zone)	mine to another when it struck a	
Underground	<i>U  /</i>	deputy who was assisting in the	
		work.	
	I	······	

1962 Australia Queensland Coal Underground	Other Unintended operation	Fatally injured when he tripped and fell against a diesel locomotive, striking his head against the metal structure of the cabin.	
Australia New South Wales Coal Underground	of Equipment	working alone on night shift on underground roadway was run over by his locomotive	
1962 Australia New South Wales Coal Underground	Other	3 men were in man transport being driven along underground roadway when rear locomotive became unhooked on a curve and ran down a grade and crashed.	
1961 Australia New South Wales Coal Underground	Other	On incline stone drift, man was killed while unloading the steel channel sections from an alligator car near the face of the drift, 700m below the surface. The alligator car passed over him.	
24/10/1960 Australia Queensland Coal Underground	Explosives	Fatally injured when explosives lying on the track were run over and exploded by the locomotive he was driving.	
28/06/1960 Australia New South Wales Coal Underground	Other	4 empty mine cars became uncoupled and ran down a gradient colliding with a battery locomotive and killing the driver	
1960 Australia New South Wales Coal Underground	Unintended operation of Equipment	2 uncertified drivers attempted to take 3 battery locomotives, coupled together, down an undulating roadway. It derailed at a safety point and one of the drivers was killed.	
21/08/1959 Australia New South Wales Coal Underground	Other	Shunter was crushed between the side of a minecar and a close roadside prop	
15/07/1959 Australia New South Wales Coal Underground	Other	9 loaded mine cars became uncoupled from a diesel locomotive and ran back down the grade, killing the operator of an electric locomotive behind.	
8/07/1959 Australia New South Wales Coal Underground	Other	Was crushed between the locomotive he was driving and the first car, when the set was struck by two runaway loaded 10 ton rail cars	
3/07/1959 Australia New South Wales Coal Underground	Other	Shunter was struck by a derailed mine car, following a collision between full and empty cars attached to a locomotive travelling in the opposite direction.	

22/02/10/20			
23/03/1959	Gas Ignition	Explosion originated when an	
United States	Explosion	explosive mix of methane and air	
Coal		was ignited by an electric arc or	
Underground		spark from the trolley wheel of the locomotive.	
20/11/1958	Electrocution	Electrocuted while fitting a cover to	
Australia	Electrocution	the control box of a coal loading	
New South Wales		machine	
Coal		machine	
Underground			
21/04/1958	Unintended operation	Was bringing a full race of coal from	
New Zealand	of Equipment	Dip top when the truck became	
Coal		derailed on a curve, tipped up one	
Underground		end and pinned him under the front	
0		eng.	
21/02/1958	Unintended operation	Killed by being struck by a loaded	
Australia	of Equipment	rake of trucks which ran out of	
New South Wales		control.	
Non-Coal			
Underground	0.1		
20/02/1958	Other	Shunter was knocked down and run	
Australia New South Wales		over by a trolley wire locomotive	
Coal		during shunting operations.	
Underground			
15/08/1957	Other	Locomotive driver was thrown from	
Australia		his seat when a collision occurred.	
New South Wales			
Coal			
Underground			
27/05/1957	Unintended	Fatally injured from fractures of the	
Australia	Operation of	pelvis and severe damage to his legs	
Queensland	Equipment	when he was crushed from a runaway	
Coal		cuddy balance wagon.	
Underground	0.1		
24/09/1956	Other	Killed when struck by electric	
Australia		locomotive when trying to replace	
New South Wales Non-Coal		derailed box truck.	
Underground			
5/07/1956	Other	Fatally injured whilst driving a train	
Australia		when the train ahead of him began to	
Queensland		reverse and as a result crushed him	
Non-Coal		between the electric mule and an air	
Underground		shovel.	
1956	Unintended	Being struck by a runaway train.	
Australia	Operation of		
New South Wales	Equipment		
Coal Un demonstration			
Underground	Ininton do damantia	Doing struck by a grant static	
1956 Australia	Unintended operation	Being struck by a runaway train	
Austrana New South Wales	of Equipment		
Coal			
Underground			
1956	Other	Crushed between roof supports and a	
Australia	5	locomotive.	
New South Wales			
Coal			
Underground			
· · · · · · · · · · · · · · ·	1	1	

22/06/1955	Other	Fatally injured when he was crushed	
Australia		between the mancha mule and the	
Queensland		leading stationary truck.	
Non-Coal			
Underground			
31/01/1955	Contact with Moving	Fatally injured whilst shunting a car	
Australia	or Rotating Plant	load of timber on No.7 level when a	
Queensland	(Guarding/Access to	piece of timber projecting from the	
Non-Coal	Danger Zone)	side of the car came into contact with	
Underground		the ventilation door frame, crushing	
_		against the frame of the mule.	
1955	Unintended operation	Taken out by a run away locomotive.	
Australia	of Equipment		
New South Wales			
Coal			
Underground			
1955	Unintended operation	Taken out by a run away locomotive.	
Australia	of Equipment		
New South Wales	I I		
Coal			
Underground			
1955	Unintended operation	Taken out by a run away locomotive.	
Australia	of Equipment		
New South Wales	or Equipment		
Coal			
Underground			
1955	Other	Crushed between rolling stock and	
Australia	Oulor	side timbers.	
New South Wales		side timbers.	
Coal			
Underground			
1955	Other	Eall off a maxing lose mative	
Australia	Ouller	Fell off a moving locomotive.	
New South Wales			
Coal			
Underground	I Inintended energien	Collision of colling stock on a	
1955 Australia	Unintended operation	Collision of rolling stock on a	
Australia	of Equipment	diamond crossing.	
New South Wales			
Coal			
Underground	Other	Deceased lost control of a	
1955 Australia	Other		
Australia		locomotive he was driving and he	
New South Wales		impacted the coal side.	
Coal			
Underground	Other		
4/06/1951	Other	Fatally injured when he fell from the	
Australia		locomotive whilst it was in motion.	
Queensland			
Non-Coal			
Underground	0.1		
20/09/1948	Other	Fatally injured when he was stuck by	
Australia		a runaway empty rake.	
Queensland			
Coal			
Underground			
1			

01/05/10/15			
21/07/1947	Contact with Moving	Fatally injured when he was trying to	
Australia	or Rotating Plant	control his horse when he either fell	
Queensland	(Guarding/Access to	of was knocked down and was	
Coal	Danger Zone)	subsequently run over by the skips.	
Underground			
29/07/1946	Unintended	Two men were fatally injured from a	
Australia	Operation of	runaway skip.	
Queensland	Equipment		
Coal			
Underground			
29/06/1942	Other	Fatally injured when he was struck	
Australia		by a runaway full skips in No. 2	
Queensland		tunnel haulage road.	
Coal			
Underground			
27/05/1942	Other	Fatally injured from internal injuries	
Australia		he received when he was struck by a	
Queensland		runaway skip when going home from	
Coal		work up No. 2 haulage road.	
Underground			
10/08/1938	Fall From Heights	Fatally injured when he slipped and	
Australia		fell in front of a loaded skip,	
Queensland		receiving injuries to his head, chest	
Coal		and arms.	
Underground			
2/06/1938	Other	Tub Train Accident.	
United Kingdom			
Coal			
Underground			