

NSW Resources Regulator

WEEKLY INCIDENT SUMMARY

Week ending Friday 22 October 2021

This incident summary provides information on reportable incidents and safety advice for the NSW mining industry. To report an incident to the NSW Resources Regulator: phone 1300 814 609 24 hours a day, 7 days a week.

At a glance

High level summary of emerging trends and our recommendations to operators.

ТҮРЕ	NUMBER
Reportable incident total	35
Summarised incident total	1

Summarised incidents

INCIDENT TYPE

SUMMARY

Dangerous incident IncNot0040916 Construction materials A worker at a sand mine was cleaning excessive buildup on the tail roller of an operating conveyor. While using a small scraper to clean the buildup off, the worker's hand got pulled into the roller by the conveyor belt. It was common practice in this workplace to go into the guarded area and clean the tail roller without isolating the conveyor.



COMMENTS TO INDUSTRY

Under no circumstances should workers enter a guarded area without implementing isolation procedures. Mine operators should review the adequacy of their guarding and isolation arrangements, to protect workers from the risk of entanglement with operating plant. Guidance on guarding requirements can be found in Australian Standard AS/NZ 4024 Safety of Machinery.

WEEKLY INCIDENT SUMMARY

Week ending Friday 22 October 2021





Other publications of interest

The incidents are included for your review. The NSW Resources Regulator does not endorse the findings or recommendations of these incidents. It is your legal duty to exercise due diligence to ensure the business complies with its work health and safety obligations.

PUBLICATION	ISSUE/TOPIC
	International (fatal)
MSHA	Mine fatality – On 1 October 2021, a 25-year-old miner was fatally injured when he entered a surge bin, used as a feed hopper, and was engulfed by material. Details
	International (other, non-fatal)
MinEx New Zealand	Broken link arm on loader A loader was lifting blocks and stacking them to one side ready to load onto a transporter. As the blocks were lowered onto the ground, the end of the link arm broke off. The broken end of the link arm projected into the air before it landed on the ground 9 metres away from the loader. Details

Note: While the majority of incidents are reported and recorded within a week of the event, some are notified outside this time period. The incidents in this report therefore have not necessarily occurred in a one-week period. All newly recorded incidents, whatever the incident date, are reviewed by the Chief Inspector and senior staff each week. For more comprehensive statistical data refer to our annual performance measures reports.

WEEKLY INCIDENT SUMMARY

Week ending Friday 22 October 2021



© State of New South Wales through Regional NSW 2021 You may copy, distribute, display, download and otherwise freely deal with this publication for any purpose, provided that you attribute Regional NSW as the owner. However, you must obtain permission if you wish to charge others for access to the publication (other than at cost); include the publication in advertising or a product for sale; modify the publication; or republish the publication on a website. You may freely link to the publication on a departmental website.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (October 2021) and may not be accurate, current or complete. The State of New South Wales (including Regional NSW), the author and the publisher take no responsibility, and will accept no liability, for the accuracy, currency, reliability or correctness of any information included in the document (including material provided by third parties). Readers should make their own inquiries and rely on their own advice when making decisions related to material contained in this publication.

DOCUMENT CONTROL

CM9 reference	DOC21/936921
Mine safety reference	ISR21-42
Date published	29 October 2021
Approved by	Deputy Chief Inspector Office of the Chief Inspector