

## NSW Resources Regulator

# WEEKLY INCIDENT SUMMARY

Week ending Friday 12 February 2021

This incident summary provides information on reportable incidents and safety advice for the NSW mining industry. To report an incident to the NSW Resources Regulator: phone 1300 814 609 24 hours a day, 7 days a week.

## At a glance

High level summary of emerging trends and our recommendations to operators.

ТҮРЕ	NUMBER
Reportable incident total	39
Summarised incident total	1

#### **Summarised incidents**

INCIDENT TYPE SUMMARY

Dangerous incident IncNot0039212 Underground metal mine An operator sustained serious injuries when the loader he was operating drove over the edge of a stope and fell 20 metres to the level below. The loader was a tele-remote loader which was being manually operated at the time. Further investigations are continuing.



Roads or other vehicle operating areas

for manually tipping material into an open stope void. The installation, inspection and maintenance of stop blocks and bunds should be considered when developing risk controls for manually tipping into stopes. Procedures for the changeover from tele-remote operation to manual loader operation should be implemented and adhered to by loader operators.

COMMENTS TO INDUSTRY

Mine operators should have a

documented safe work procedure

#### WEEKLY INCIDENT SUMMARY

Week ending Friday 12 February 2021

#### NSW Resources Regulator

**Note:** While the majority of incidents are reported and recorded within a week of the event, some are notified outside this time period. The incidents in this report therefore have not necessarily occurred in a one-week period. All newly recorded incidents, whatever the incident date, are reviewed by the Chief Inspector and senior staff each week. For more comprehensive statistical data refer to our annual performance measures reports.

© State of New South Wales through Regional NSW 2020 You may copy, distribute, display, download and otherwise freely deal with this publication for any purpose, provided that you attribute Regional NSW as the owner. However, you must obtain permission if you wish to charge others for access to the publication (other than at cost); include the publication in advertising or a product for sale; modify the publication; or republish the publication on a website. You may freely link to the publication on a departmental website.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (May 2020) and may not be accurate, current or complete. The State of New South Wales (including Regional NSW), the author and the publisher take no responsibility, and will accept no liability, for the accuracy, currency, reliability or correctness of any information included in the document (including material provided by third parties). Readers should make their own inquiries and rely on their own advice when making decisions related to material contained in this publication.

DOCUMENT CONTROL	
CM9 reference	DOC21/104613
Mine safety reference	ISR21-06
Date published	19 February 2021
Approved by	Chief Inspector Office of the Chief Inspector